

TIME 0635Z 20 FEB 65

SECRET

TO : DIRECTOR

FROM : 25X1A

ACTION:

INFO :

FOR 0708Z 20 FEB 65

OPS 1-10 DB

IN 73004

25X1A
25X1A
25X1A

PRIORITY

INFO

SITE

1700

25X1A

A. 00450

B. FAIR

C. NO MAJOR PROCESSING TROUBLES ENCOUNTERED. SOME PROCESSING STREAKS AND PIN HOLES NOTED. CAMERA STATIC ON 9-R BURSTING ALONG BOTH EDGES FROM HEAD TO TAIL, APPROX 1 INCH IN FROM EDGES. MINUS DENSITY MARKS ON 9-L, 2 AND 3/4 INCHES IN FROM THE CLOCK EDGE, AND REPEATING EVERY 1 AND 3/4 INCHES. PLUS DENSITY LINE ON 9-R-PARTS, 1-2-3 ONLY, AND IS 3 AND 3/8 INCHES IN FROM THE OUTBOARD EDGE. METERING TROUBLE ON 9-L-THE FIRST TWO FRAMES ARE OVERLAPPED.

END OF MSG

EDD ☒
RS ☒
RP ☒
KB ☒
WC ☒
DB ☒
NM ☒
PA ☒
RG ☒